

DD/A Engistry
82-0606/1

19 March 1982

MEMORANDUM FOR: Deputy Director for Administration

in 24

VIA:

Comptroller

(2)

FROM:

James H. McDonald Director of Logistics 46 ≅

SUBJECT:

Transfer of Responsibility for

))

띴

and the 2430 E Street

Complex

- 1. Paragraph 4 of this memorandum contains a recommendation for your approval.
- 2. During the past two years, the Office of Logistics has aggressively pursued the General Services Administration (GSA) to improve the living conditions and general maintenance being provided to and the 2430 E Street Complex. These buildings have suffered from a lack of proper maintenance over the years to the point that the health and safety of our employees is a major concern to management. Although there have been improvements during the past year in correcting minor deficiencies, we have not been successful in having GSA provide the major capital improvements that are needed in these buildings. In addition, it is unlikely that GSA can provide the Agency with the level of service required in the future.
- To ensure the level of support needed for these facilities, we believe it will be necessary for the Agency to assume responsibility for the maintenance and operation of and the 2430 E Street Complex. To the maximum extent possible, we would rely on contracted services to provide the support. There are, however, major resource requirements involved. Assuming implementation in FY 1984, we project recurring costs to exceed our Standard Level User Charge payment of \$2.2 million to GSA by an additional \$2.0 million, including startup costs of \$1.7 million. In addition to the budgetary costs, we believe seven new staff positions (two at and five at the 2430 E Street Complex) will be required initially to provide the management services necessary in assuming the maintenance and operation responsibilities. The possibility exists that in the future some of the positions at the 2430 E Street Complex could be reduced as the major capital improvements are completed. At these resource levels, we can expect the habitability and upkeep to improve.

STAT

STAT

STAT

STAT

OL 2 1242

STAT

STAT

SUBJECT:	Transfer of Responsibility for the 2430 E Street Complex	and
intent to you sign Services	Based on GSA's inability to properly supervised the resources required, it is the attached letter to the Administrator Administration, requesting that the response and operation of the above the second contraction of t	recommended that r, General ponsibility for
assigned	enance and operation of the above-mention the CIA.	oned buildings be
Attachmen	James H. McDonald	
CONCUR:		
Comptrolle	•	Date
3	ion: L - Addressee, w/att L - Compt, w/att L - D/L (Official), w/att	

ว

CENTRAL INTELLIGENCE AGENCY

WASHINGTON, D.C. 20505

The Honorable Gerald P. Carmen Administrator General Services Administration Washington, D.C. 20405

Dear Mr. Carmen:

It has come to my attention that the National Capital Region recently invited bids for providing custodial service for certain Federal buildings, including our Central, East, South, and buildings. The invitation to bid is numbered GS-11C-20100.

STAT

We are concerned that a commercial contract for providing cleaning services in these buildings will have a serious adverse impact on the Central Intelligence Agency. As you know, our security requirements for unescorted access to CIA buildings include status as a U.S. citizen, completion of a full background investigation, and a polygraph interview. The clearance process is time consuming and costly, and the CIA would face the partial or complete loss of essential services and significant expense if clearances cannot be obtained or rapid turnover of personnel is experienced. Our only alternative consistent with security considerations would require providing escorts to uncleared personnel. At this time, we have neither the money nor the human resources to expand our escort program.

In addition to the custodial services, we would like to address the present situation regarding the maintenance and operations of these facilities. The amount of funds that the General Services Administration has been able to budget and the resources that GSA has available to properly maintain these buildings has diminished over the years to the point that required capital improvements to the buildings cannot be undertaken until FY 1985. The Agency has repeatedly identified our major concerns, including the heating, ventilation, and air-conditioning systems; roofing and structural repairs; and utility upgrades and the health and safety deficiencies.


In view of this, we request that GSA consider authorizing the CIA to assume responsibility for the maintenance and operation of these four buildings.

The Honorable Gerald P. Carmen

We feel the Agency is in a better position to cope with security requirements, building requirements, and allocation of resources within the buildings. Also, we believe the opportune time to assume responsibility would be shortly after the implementation of the maintenance and operation contract on Accordingly, and until a decision is reached, we ask that cleaning service continue to be provided by GSA personnel who are cleared by this Agency and that every effort be made to improve the present conditions of these facilities.

STAT

Harry E. Fitzwater Deputy Director for Administration



DDA 82-0259/1

RESCHOOL GODDEN

3 February 1982

MEMORANDUM FOR: Deputy Director for Science and Technolog

FROM:

Harry E. Fitzwater

Deputy Director for Administration

SUBJECT:

Progress Report on the OTS Inspection Report

Recommendation 3

REFERENCE:

Memo dtd 7 May 81 to DDA fr DDCI, same subj

The Office of Logistics (OL) has been working with various levels of the General Services Administration (GSA) to improve the habitability and upkeep of the 2430 E Street, Washington, D.C., complex. Priority has been given to correcting the safety deficiencies cited in the Safety Group, Office of Security (SG/OS) occupational health and safety inspection report. GSA has been responsive to the report and has taken corrective action to repair minor deficiencies in the electrical and fire protection systems.

- 2. The 2430 E Street complex has suffered from a lack of proper maintenance over the years, and this has led to the deterioration of the facility. Additionally, the shortage of space, compounded by the use of hallways, stairwells, and mechanical rooms as storage areas has fostered poor housekeeping practices. Upkeep has improved somewhat during the past months, but is still at an unacceptable level and continued improvement is being made by OTS and GSA.
- 3. Although there has been an improvement during the past six months in correcting minor deficiencies, no major project undertaking to improve the three buildings has been taken by GSA. OL has been informed by GSA that there is no money budgeted for capital improvements to the complex through FY 1985. GSA has indicated that they will endeavor to do painting and habitability improvements during the next nine months. Although no money for capital improvements has been budgeted for the complex, GSA had indicated that they may be able to initiate projects up to \$100,000 per building in FY 1982. OL had identified to GSA items of major concern including the HVAC systems, roofing and structural repairs, and utility upgrades. GSA is reviewing the final report submitted by a consulting engineering firm hired to evaluate the condition of the complex.
- 4. OL has met with GSA to review the design for the construction of a fire escape to service the first and second floors of the East Building. The design is nearly complete and construction should begin in the spring of 1982.

Approved For Release 2008/08/05 : CIA-RDP85B00552R001100010041-9 In summary, OL will continue pursuing various actions with GSA to improve the 2430 E Street complex. The amount of money GSA will be able to budget for improvements will decide the extent of the improvements. OL will continue to provide assistance to GSA in identifying priority items. With funding and continued assistance from GSA, improvements to the facility should continue. **STAT** DDCI EXDIR IG

Approved For Release 2008/08/05 : CIA-RDP85B00552R001100010041-9

Approved For Release 2008/08/05 : CIA-RDP85B00552R001100010041-9

Du/A REGISTLY
FILE: 40

DDA 82-0259/1

3 February 1982

MEMORANDUM FOR: Deputy Director for Science and Technology

FROM:

Harry E. Fitzwater

Deputy Director for Administration

SUBJECT:


Progress Report on the OTS Inspection Report

Recommendation 3

REFERENCE:

Memo dtd 7 May 81 to DDA fr DDCI, same subj

- 1. The Office of Logistics (OL) has been working with various levels of the General Services Administration (GSA) to improve the habitability and upkeep of the 2430 E Street, Washington, D.C., complex. Priority has been given to correcting the safety deficiencies cited in the Safety Group, Office of Security (SG/OS) occupational health and safety inspection report. GSA has been responsive to the report and has taken corrective action to repair minor deficiencies in the electrical and fire protection systems.
- 2. The 2430 E Street complex has suffered from a lack of proper maintenance over the years, and this has led to the deterioration of the facility. Additionally, the shortage of space, compounded by the use of hallways, stairwells, and mechanical rooms as storage areas has fostered poor housekeeping practices. Upkeep has improved somewhat during the past months, but is still at an unacceptable level and continued improvement is being made by OTS and GSA.
- 3. Although there has been an improvement during the past six months in correcting minor deficiencies, no major project undertaking to improve the three buildings has been taken by GSA. OL has been informed by GSA that there is no money budgeted for capital improvements to the complex through FY 1985. GSA has indicated that they will endeavor to do painting and habitability improvements during the next nine months. Although no money for capital improvements has been budgeted for the complex, GSA had indicated that they may be able to initiate projects up to \$100,000 per building in FY 1982. OL had identified to GSA items of major concern including the HVAC systems, roofing and structural repairs, and utility upgrades. GSA is reviewing the final report submitted by a consulting engineering firm hired to evaluate the condition of the complex.
- 4. OL has met with GSA to review the design for the construction of a fire escape to service the first and second floors of the East Building. The design is nearly complete and construction should begin in the spring of 1982.





DD/A 1. 34.11 82-0259

97 777 778

MEMORANDUM FOR: Deputy Director for Administration

FROM:

James H. McDonald

Director of Logistics

SUBJECT:

Progress Report on the Office of Technical Service Inspection Report Recommendation 3

REFERENCE:

Memo for DDA from DDCI, dtd 7 May 1981, Same

Subject (DD/A 81-0067/5; OL 1 1995)

- l. The attached blind memorandum is a progress report on our efforts to improve the living conditions at the 2430 E Street Complex. The report, which addresses the concerns of the Deputy Director of Central Intelligence regarding Recommendation 3 of the Inspector General's report, is for your information, but we have prepared it as a blind memorandum in case you decide to forward it to the DDCI.
- 2. For your information, the Real Estate and Construction Division, OL, and the Logistics Services Division, OL, have been and will continue pursuing various actions to improve the habitability and upkeep of the 2430 E Street, Washington, D.C., Complex.

James H. McDonald

Attachment

cc: C/SG/OS, w/att

